Moint of the Ubnited States.

Philadelphia, 11th Och 1879

Hon A. Loudon Enonder

DearSir

report on the bullion received from the W.S. much Deuver:

Formerly the bullion was received tough and good now part of it is brittle and bad. The brittleness is caused by volatile substances contained in the buller and produces loss to the government. The volatile substances are Easely removed and without much loss of gold when the bullion is in its natural state, but roben mel ted into bars very difficult to remove. This was the Epperience of This minh in 1863 and 1864 when the government suffered great losses on account of volatilization, The Denon much Should I think be required to tougher all their bullion roben first received,

The Dewoor meur brittle bars received

here last month, after being delivered to the melter or Referrer, work carefully reweighed the Standard weight Estimated, and then taken to the deposit melting room and toughened with the following results Use of he before Jong brening on \$ 2366.45 " after " " 234230 Loss in 1 24,15 Standard Weight Before Jongheningons, 2394.41 after " # 2391.45 Nop of gold in " 2,96 Submitted ben Pespet fully Ho. S. Loudmans Weigh lolert

8/2/2 Mint of the United States, PHILADELPHIA. Oct 11, 1879 No. of Enclosures, Rec? Oct. 11th 1879.

[Abstract:] Reports the brittle & bad quality of the gold bullion received... 812 ½

Mint of the United States, Philadelphia, October 11, 1879

Hon. A. Loudon Snowden

Dear Sir

At your request submit the following report on the bullion received from the U.S. Mint Denver.

Formerly the bullion was received tough and good now part of it is brittle and bad. The brittleness is caused by volatile substances contained in the bullion and produces loss to the government. The volatile substances are easily removed and without much loss of gold when the bullion is in its natural state, but when melted into bars very difficult to remove. This was the experience of this Mint in 1863 and 1864 when the government suffered great losses on account of volatilization. The Denver Mint should I think be required to toughen all their bullion when first received. The Denver Mint brittle bars received here last month after being delivered to the Melter & Refiner were carefully reweighted, the Standard weight estimated and then taken to the deposit melting room and toughened with the following results.

Weight before toughening ozs.		2366.45
" after "	"	2342.30
Loss in "	44	24.15
Standard Weight		

Before toughening ozs. 2394.41
After " 2391.75
Loss of gold in " 2.96

Submitted Very Respectfully H.S. Cochran

Weight Clerk